Number of beneficiaries (students & teachers) who will benefit from the project: 254 student & 6 teachers

The Number of Stalls: The new toilet facility will consist of four (04) stalls for students and teachers.
Dimensions: The entire toilet will be 4 meters deep. The length will be four meters long by 1meter 10cm wide
Community Contribution: The local community through the Parents Teachers Association (PTA) has pledge to provide voluntary unskilled labour in excavating the toilet pit as their contribution for the project.

A Brief History about St Gloria primary school
St Gloria primary school is located in Bova village community, Southwest region of Cameroon. Bova is a peasant community in Buea sub division with a growing population of over 6000 inhabitants with very low income, high birth rate and high illiteracy rate. St Gloria, primary school is mostly attended by poor village children of ages 5-12 years, most of whom are orphans, girls, and internally displaced children living with local relatives. 254 pupils attend St Gloria primary school, of which 132 are girls and 122 boys based on the head mistress.
The poor peasant community (the management of the school) are doing their best to ensure their children have access to education by struggling to raise funds to pay six (06) teachers employed to teach in the school. The poor peasant community is unable to raise enough funds to construct a new toilet facility for vulnerable children attending St Gloria primary school. The existing toilet facility that was constructed so many years ago is full and it may collapse at any time. Feces are litter everywhere around the toilet. Children have been restricted from using the toilet facility as it may collapse at any time. The absence of toilet facility at St Gloria primary school has compelled many pupils to defecate in nearby farms, streams, behind their classrooms and pavements. It is common to see children practicing open defecation around the school environment, especially the younger scholars behind classrooms. This has made the school environment not conducive for teaching learning process due to bad odour from the school environment especially behind classrooms.